Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080145-3

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11537

RECEIVED FROM PLANT #1

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	C R	ACCT. OR W.O. NO. / S.O. NO.
	322	0	16	0	21					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
5	733161 Bracket Muffle	5		
	IPS #A003393			
	To supersede Rec. Insp. Report #11529			

RECEIVED BY: [illegible] HMC 1053

INSPECTED BY: DWA DATE 3/11/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11539

RECEIVED FROM PLANT #1

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	C R	ACCT. OR W.O. NO. / S.O. NO.
	322	NCT 1	901	0	22					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
2.0	733258 Shipping Flange	2.0		
	IPS AC1787			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080145-3

RECEIVED BY: [illegible]

INSPECTED BY:

DATE 3-11-57

REJECTS RETURNED ON SHIP. MEMO NO.